

VEHICLE INSPECTION REPORT

SF19NFJ

KUBOTA F3090

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	05/04/2019	Fuel Type	Diesel	Body Style	RIDE ON MOWER
Year	2019	Colour	ORANGE	Gearbox	HYDROSTATIC
Mileage	2,831 Hours Not Warranted	VIN	11389	Axle Combi	4x2

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



