

VEHICLE INSPECTION REPORT

SF19NFM

KUBOTA F3090

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	04/04/2019	Fuel Type	Diesel	Body Style	Mowing Machine
Year	2018	Colour	ORANGE	Gearbox	HYDROSTATIC
Mileage	1,727 Hours Not Warranted	VIN	11502	Axle Combi	4x2

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK