

VEHICLE INSPECTION REPORT

DK17KXH

Man TGS 26.320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/03/2017

VIN WMA18SZZ7HY357735

Gearbox MANUAL

Year 2017

Body Style Curtainside

Axle Combi 6x2

Mileage 424,160 Km Warranted

Keys 1

Steering Combi Rear-Lift Steer

Fuel Type Diesel

MOT Due 30/04/2026

Rear Suspension Air

Colour BLUE

Cab Type DAY CAB

WARNING LIGHT ON DASH MOFFETT BRACKETS, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features


- Bluetooth connection
- Cruise control
- Park assist camera
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osf
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Not Thru Paint

6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK