

VEHICLE INSPECTION REPORT

SJ16XLW

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	25/05/2016	Colour	YELLOW	Cab Type	DAY CAB
Year	2016	VIN	XLRAEL3700L448976	Gearbox	AUTOMATIC
Mileage	160,584 Km Warranted	Body Style	Gully Emptier	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/03/2026	Rear Suspension	Steel

WHALE BODY, FULL SIZE BACK DOOR

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Sill os
Rusted
Over 5mm

4: Wing osf
Cracked
Replace



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Rusted
Over 5mm

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door Moulding nsf
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK
Windows	OK		Radio	OK
			Steering	OK