

VEHICLE INSPECTION REPORT

OY69UCX

Land Rover Discovery 2.0 SD4 240PS HSE LUXURY

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Margin
V5 Buyer To Apply

nama
GRADU
2

Details

Reg. date	03/09/2019	Body Style	SUV	Gears	8
Year	2019	MOT Due	Expired	Axle Combi	4x4
Mileage	38,911 Miles Not Warranted	CAP Clean	£19,000.00	Steering Combi	Steer
Fuel Type	Diesel	CAP Average	£17,650.00	Rear Suspension	Air
Colour	BLACK	CAP Below	£16,250.00		
VIN	SALRA2AN9L2416494	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH REAR MOUNTED SCREENS, MERIDIAN HIFI

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Bluetooth connection
- Navigation system
- Reverse parking aid
- USB/iPod interface
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- 3x3 point rear seat belts
- Drivers airbag
- Tyre pressure monitor
- Cruise control
- Park assist camera
- Service indicator
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Rear armrest
- ABS
- ESP
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front armrest
- Rear electric windows
- Blind spot information
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Rear wiper
- Radio/CD
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip

2: Door osf
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
1 To 5

4: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	Yes
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		