

VEHICLE INSPECTION REPORT

YD71WHC

Iveco S-Way 570

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/10/2021

Year 2021

Mileage 445,043 Km Not Warranted

Fuel Type Diesel

Colour BLUE

VIN WJMS62NW90C454940

Body Style Tractor Unit

MOT Due 31/10/2026

Cab Type AS SLEEPER

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

SLIDING 5TH WHEEL, FRIDGE, MICROWAVE

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3






OSO4



Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Missing
Replace



3: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint

4: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



5: Qtr Panel osr
Dented
Over 30mm

6: Door osf
Dented
With Paint Damage



7: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		