

VEHICLE INSPECTION REPORT

YD71WHB

Iveco S-Way 570

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/10/2021

Year 2021

Mileage 481,544 Km Not Warranted

Fuel Type Diesel

Colour BLUE

VIN WJMS62NW70C455066

Body Style Tractor Unit

MOT Due 31/10/2026

Cab Type AS SLEEPER

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

WARNING LIGHT ON DASH SLIDING 5TH WHEEL, FRIDGE, MICROWAVE

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4


Features

- Digital radio
- Air conditioning


Photos







Condition Check



Damage Photos



1: Door osf
Scratched
Over 25mm Thru Paint



2: Panel Rear
Scratched
UpTo 25mm Thru Paint



3: Panel Rear
Scratched
Over 25mm Thru Paint

4: Panel Rear
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage

6: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK